



Korpus formy

Mold base

100x130




Wymiary i tolerancje
Dimensions and tolerances



	A	B	C
PK	108	52	80


PK 01



PK 01 – 100 x 130 x h / material

22	1730
	2312
	2085


PK 11




PK 01 – 100 x 130 x h / material

22	1730
	2312
	2085


PK 02



PK 12




PK 21



PK 21 – 100 x 130 x h / material

12	1730
17	2312
	2085



PK 22



PK 22 – 100 x 130 x h / material

12	1730
17	2312
	2085

PK 03



PK 03 – 100 x 130 x h / material

9	1730
12	2083
17	2085
22	2162
27	2311
36	2312
46	2738
56	Toolox33
	Toolox44
	2738HH
	2714HH

Podcięcia do demontażu na życzenie.
Corner undercuts upon request.



Material info





Korpus formy

Mold base

100x130

PK 31



PK 31 – 100 x 130 x h / material

9	1730
12	2083
17	2085
22	2162
27	2311
36	2312
46	2343
56	2738
	2767
	Toolox33
	Toolox44
	2738HH
	2714HH



Podcięcia do demontażu na życzenie.
Corner undercuts upon request.



Material info





PK 04



PK 04 – 100 x 130 x h / material

6	1730
12	2312
17	2085


PK 05





PK 05 – 100 x 130 x h / material

27	1730
36	2085
46	

PK 55




PK 06





PK 06 – 100 x 130 x h / material

6	1730
	2085

PK 65



PK 07



PK 07 – 100 x 130 x h / material

9	1730
	2312
	2085

PK 75

