



Korpus formy

Mold base

96x96




Wymiary i tolerancje
Dimensions and tolerances



	A	B	C
PKA	74	24	74


PKA 01



PKA 01 – 96 x 96 x h / material

17	1730
22	2312
	2085



PKA 11



PKA 11 – 96 x 96 x h / material

17	1730
22	2312
	2085



PKA 02



PKA 02 – 96 x 96 x h / material

17	1730
	2312
	2085



PKA 12



PKA 12 – 96 x 96 x h / material

17	1730
	2312
	2085



PKA 025



PKA 025 – 96 x 96 x h / material

17	1730
22	2312
	2085



PKA 125



PKA 125 – 96 x 96 x h / material

17	1730
22	2312
	2085

PKA 21



PKA 21 – 96 x 96 x h / material


17	1730
	2312
	2085

Korpus formy

Mold base

96x96



PKA 22



PKA 22 – 96 x 96 x h / material

17	1730
	2312
	2085

PKA 03



PKA 03 – 96 x 96 x h / material

12	1730
17	2083
22	2085
27	2162
36	2311
46	2312
56	2738
	Toolox33
	Toolox44
	2738HH
	2714HH



Podcięcia do demontażu na życzenie.
Corner undercuts upon request.



Material info



PKA 31



PKA 31 – 96 x 96 x h / material

12	1730
17	2083
22	2085
27	2162
36	2311
46	2312
56	2343
	2738
	2767
	Toolox33
	Toolox44
	2738HH
	2714HH



Podcięcia do demontażu na życzenie.
Corner undercuts upon request.



Material info





PKA 04



PKA 04 – 96 x 96 x h / material

12	1730
17	2312
22	2085



PKA 05



PKA 05 – 96 x 96 x h / material

36	1730
46	2085
56	
66	



PKA 06



PKA 06 – 96 x 96 x h / material

9	1730
	2085

PKA 07



PKA 07 – 96 x 96 x h / material

12	1730
	2312
	2085