



Korpus formy

Mold base

126x156





Wymiary i tolerancje
Dimensions and tolerances



	A	B	C
PKA	124	60	94


PKA 01



PKA 01 – 126 x 156 x h / material

22	1730
27	2312
	2085


PKA 11



PKA 11 – 126 x 156 x h / material

22	1730
27	2312
	2085



PKA 02



PKA 02 – 126 x 156 x h / material

22	1730
27	2312
	2085


PKA 12



PKA 12 – 126 x 156 x h / material

22	1730
27	2312
	2085



PKA 21



PKA 21 – 126 x 156 x h / material

22	1730
27	2312
	2085


PKA 22



PKA 22 – 126 x 156 x h / material

22	1730
27	2312
	2085

PKA 03



PKA 03 – 126 x 156 x h / material

17	1730
22	2083
27	2085
36	2162
46	2311
56	2312
66	2738
	Toolox33
	Toolox44
	2738HH
	2714HH

Podcięcia do demontażu na życzenie.
Corner undercuts upon request.



Material info





Korpus formy

Mold base

126x156

PKA 31



Podcięcia do demontażu na życzenie.
Corner undercuts upon request.





Material info



PKA 31 – 126 x 156 x h / material

17	1730
22	2083
27	2085
36	2162
46	2311
56	2312
66	2738
	2767
	Toolox33
	Toolox44
	2738HH
	2714HH



PKA 04



PKA 04 – 126 x 156 x h / material

17	1730
22	2312
27	2085
36	

PKA 05




	A	B
PKA 05	29	68



PKA 05 – 126 x 156 x h / material

36	1730
46	2085
56	
66	
76	
86	
96	

PKA 55



PKA 06




	A	B	C
PKA 06	80	40	66



PKA 06 – 126 x 156 x h / material

9	1730
	2085

PKA 65



PKA 07



	A	B	C	D
PKA 07	80	40	66	130

PKA 07 – 126 x 156 x h / material

17	1730
	2312
	2085

PKA 75

