



Korpus formy

Mold base

896x1096



Wymiary i tolerancje
Dimensions and tolerances





	A	B	C
PKA	1008	890	808

PKA 01




PKA 11



PKA 11 – 896 x 1096 x h / material

56	1730
	2312
	2085


PKA 02




PKA 12



PKA 21





PKA 22



PKA 22 – 896 x 1096 x h / material

56	1730
	2312
	2085

PKA 03



PKA 03 – 896 x 1096 x h / material

56	1730
66	2083
76	2085
86	2162
96	2311
116	2312
136	2738
156	Toolox33
176	Toolox44
196	2738HH
216	2714HH
236	
256	

Podcięcia do demontażu na życzenie.
Corner undercuts upon request.



Material info




Korpus formy



Mold base

896x1096

PKA 31





PKA 04



PKA 04 – 896 x 1096 x h / material

66	1730
86	2312
	2085



PKA 05



PKA 05 – 896 x 1096 x h / material

136	1730
156	2085
176	
196	
236	
276	


PKA 55




PKA 55 – 896 x 1096 x h / material

136	1730
156	2085
176	
196	
236	
276	

PKA 06




	A	B
PKA 06	940	700




PKA 06 – 896 x 1096 x h / material

36	1730
	2085

PKA 65




	A	B
PKA 65	940	640




PKA 65 – 896 x 1096 x h / material

36	1730
	2085

PKA 07




	A	B	D
PKA 07	940	700	1058




PKA 07 – 896 x 1096 x h / material

46	1730
	2312
	2085

PKA 75



	A	B	D
PKA 75	940	640	1058



PKA 75 – 896 x 1096 x h / material

46	1730
	2312
	2085